

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Boise Basin Mercantile Company Block
Northeast corner of Main and Commercial Streets
Idaho City
Boise County
Idaho

HABS No. ID-13

Documentation: 6 sheets (1974, including site plan, plans, elevations, details)
5 exterior photos (1976)
2 interior photos (1976)
1 photocopy (ca. turn of the 20th c.)
11 data pages (1974)
1 set of field records (1974, including 1 field notebook,
35 field photos)

- ID-13-1 Duane Garrett, Photographer 1976
EAST (FRONT) ELEVATION
- ID-13-2 Duane Garrett, Photographer 1976
NORTHWEST CORNER
- ID-13-3 Duane Garrett, Photographer 1976
NORTHEAST CORNER
- ID-13-4 Duane Garrett, Photographer 1976
SOUTH ELEVATION
- ID-13-5 Duane Garrett, Photographer 1976
IRON SHUTTERED DOORWAY, NORTHEAST
CORNER OF NORTH ELEVATION
- ID-13-6 Duane Garrett, Photographer 1976
INTERIOR IRON SHUTTERED DOOR BETWEEN
FORMER BANK AND MERCANTILE STORE
- ID-13-7 Duane Garrett, Photographer 1976
OLD BANK SAFE IN WEST WALL OF MAIN
BANKING ROOM
- ID-13-8 Photocopy of old photo shows the interior
view of the Boise Basin Mercantile store,
circa turn of the 20th century. Original
photograph at Boise Basin Museum, Idaho City,
Idaho